



BBMP ENGINEERING DEPARTMENT
Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
3

Ward Name
Atturu

Street ID
W0349, W0351, W0347, W0212

Street Name
7th Main Rd, G M Palya, S Krishnappa Lyt, R H B Colcny 2nd Main Rd, NA

Significant Landmark
7th cross road of attur layout

Segment No.
3/C-W0349/S075228

Total Length (m)
229.86

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	229.86	77.567283	13.103355	77.569354	13.103091	W0299	W0351

Work Details

History of Road / Lane / Circles

Name of the Work
Change of place for Improvements to roads and side drain 7th cross road of attur layout in ward no 03 Yelahanka Satellite Town Sub division Yelahanka

Sanctioned Estimated Amount (Rs.)
1500000

Sanctioned Year
2017

Year
2017 - 2018

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Change of place for Improvements to roads and side drain 7th cross road of attur layout in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone

Job No. / Work Code
003-17-000052

Work Order No.
EE (YNK.D)E-PMT-09/WO/58/2017-18

Work Order Date
14/06/2017

Period of Extention
90 DAYS

Defect Liability Period From
10/10/2017

Defect Liability Period To
09/10/2018

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
K RAVIKUMAR

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Phone No.

E-Mail ID

Zone: YELAHANKA

Ward No: 3

Ward Name: Atturu

Street ID: W0349, W0351, W0347, W0212

AE-03

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕರ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಕೆ. ಬೆಂಗಳೂರು-106

Field Inspection Details

Number of Trees

Any Other Information

Name

0

CHANDRAKANT

Date of Inspection

Remarks

04/11/2017

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Zone: YELAHANKA

Ward No: 3

Ward Name: Atturu

Street ID: W0349,
W0351,
W0347,
W0212

AE-02

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು

ಯು.ಕೆ.ಎ. ಸುಪನಗರ ಸುವರ್ಣಾಂಗ,

ಬಿ.ಬಿ.ಎ.ಕೆ. ಬೆಂಗಳೂರು-105

Side 10 to

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAI AH	08/11/2017	08/12/2017	COMPLETED
SE	VASU K M	08/11/2017	04/12/2017	COMPLETED
EE	VASU K M	04/11/2017	04/12/2017	COMPLETED
AEE	ASHOK	04/11/2017	04/12/2017	COMPLETED
AE	CHANDRAKANTH	04/11/2017	04/12/2017	COMPLETED
AE	CHANDRAKANTH	04/11/2017	04/12/2017	COMPLETED

Accountant
AE-03



ನಿರ್ದೇಶಕ ಕಾರ್ಯಪಾಲಕ ಅಧ್ಯಯನಾಧಿಕಾರಿ
ಮಹಾನಗರ ಪಾಲಿಕೆ, ಬೆಂಗಳೂರು-105